



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

February 25, 1985

Mr. Ronald H. Baldwin
Interstate Brick Company
9780 South 5200 West
West Jordan, Utah 84084

Dear Mr. Baldwin:

RE: Receipt of Annual Operations and Progress Reports

Please be informed that the Division of Oil, Gas and Mining has received your Annual Operations and Progress Reports (Form MR-3) for the following mines: Long Canyon Mine, ACT/049/007, Jim Gay Mine, ACT/049/005, Powell Mine, ACT/049/004, Black Mine, ACT/049/003, Smokey Joe Mine, ACT/049/002, Utah County, Utah; Fivemile Pass Mine, ACT/045/006, Tooele County, Utah; Henefer Mine, ACT/043/002, Summit County, Utah; Big Cottonwood Mine, ACT/035/003, Salt Lake County, Utah; Koosharem Mine, ACT/031/002, Piute County, Utah; Montello Mine, ACT/003/004, Box Elder County, Utah; White Mountain Mine, ACT/001/005, Beaver County, Utah.

Your cooperation in submitting this information in a timely manner is appreciated.

Best regards,

Ronald W. Daniels
Acting Administrator
Mineral Resource Development
and Reclamation Program

PGL/btb
0122R-17

Rec'd 2/13/85

ANNUAL OPERATIONS AND PROGRESS REPORT

From Month/Year January 1, 1984
to Month/Year December 31, 1984

(To be submitted for each mining operation at the end of each calendar year to the Division at this address:)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
(801) 538-5340

OPERATOR: Interstate Brick Co. MINE NAME: Black

ADDRESS: 9780 South 5200 West
West Jordan, UT 84084

PERMIT NUMBER AND DATE OF PERMIT: ACT/049/003

REPRESENTATIVE: Ronald H. Baldwin

SECTION(S): 36; 1 TOWNSHIP(S): 6 South; 7 South RANGE(S): 1 West SLBM

MINERAL(S) MINED: Clay

STATE AND/OR FEDERAL MINERAL LEASE NUMBERS: State Mineral lease numbers
7280, 17215, 17637, 17992, 18038

SPECIAL USE PERMITS AND/OR RIGHTS-OF-WAY: None

Section 40-8-15 and Rule M-8 of the Utah Mined Land Reclamation Act, requires each operator to include with this report an up-dated map and plan prepared in accordance with Rule M-3, as outlined in the requirements for annual report maps in Appendix I, providing a detailed status of all mining and reclamation activities which have occurred during the past year.

The report should include:

MINING:

(a) Tabulation of acreage disturbed (by pits, roads, facilities, etc.) during the report period with illustration on a current map.

Acreage

$$\begin{array}{r} -0- \\ \hline -0- \\ \hline -0- \\ \hline -0- \\ \hline -0- \end{array}$$

(b) Tabulation of acreage affected to date (by years).

Acreage (Total

Unknown

55

22

11

99

88

10

10

10

10

(c) Tabulation of all topsoil (new) stockpile volumes (see chart below) and date of stockpiling.

SOIL TABULATION CHART

Area			
1	2	3	etc.

No mining was done

in 1984.

Soil Tabulation Chart (continued)

Area Affected (in mining sequence)	Area			
	1	2	3	etc.
Storage Location	N/A			
Area Where Soil Has Been Used (if not stored)				
Running Total (all stockpiles) (yd ³ or ac ft)				
Short-term				
Long-term				

*Of previously stripped area recently reclaimed.

(d) Tabulation of all (newly removed) out-of-pit spoil volumes, date of placement and illustration on a map.

<u>Area</u>	<u>Date</u>	<u>Acreage</u>
N/A		

(e) Tabulation of quantity of commodity mined.

	<u>Commodity</u>	<u>Tonnage</u>
(Mined)	Clay	0
(Milled)	Clay hauled from existing stockpile	8313

(f) Description of any new construction during the report period with illustration on a map, including, but not limited to:

- Buildings and support facilities.
None

- Roads.
None

3. Diversion ditches, collector ditches, interceptor ditches, etc.

None

4. Culverts.

None

5. Sediment ponds, containment ponds.

None

6. Monitoring sites (vegetative, air quality, surface subsidence, surface water or ground water, etc.).

None

7. Topsoil stockpiles.

None

(g) Description of any environmental problem areas with a proposed plan for mitigation and illustration on a map, including, but not limited to:

1. Pit stability problems.

None

2. Subsidence.

None

3. Accidental water discharge, dam failure, etc.

None

4. Slumping, sliding or erosion.

None

5. Revegetation problem areas.

None

6. Existence and location of unsuitable (toxic) overburden.

None

RECLAMATION:

(a) Tabulation of the acreage reclaimed during the report period with illustration on a map, distinguishing between:

1. Backfilled, graded and contoured areas.

Area

Acreage

None

2. Topsoiled areas.

Area

Acreage

None

3. Seeded areas.

<u>Area</u>	<u>Acreage</u>
None	

4. Reseeded areas (areas previously seeded, then seeded again).

<u>Area</u>	<u>Acreage</u>
None	

(b) Tabulation of total acreage reclaimed (seeded with permanent seed mix) to date by years with illustration on an updated map:

<u>Year</u>	<u>Acreage</u>
1975	-0-
1976	-0-
1977	-0-
1978	-0-
1979	-0-
1980	-0-
1981	-0-
1982	-0-
1983	-0-
1984	-0-

(c) Description of the reclamation procedures used during the report period, including:

1. Average depth of topsoil applied.

None

2. Type of seed (species) used for seeding during the report period.

None

3. Date of seeding during the report period.

Spring N/A

Fall _____

4. Seeding procedures used.

(Hand broadcast or drilled or any other).
N/A

5. Rate of seed application.

Pounds Per Acre of Pure Live Seed (PLS) (if varied, please explain)
N/A

6. Type and rate of fertilizer applied.
N/A

7. Type and rate of mulch applied.
N/A

8. Rate of irrigation water applied, if any. Please describe any type of sprinkling, or water applied (water truck, etc.).
N/A

9. Revegetation test plot information.

(Cover, density, productivity, etc.)
None

10. Soil analysis results.

None

(d) Description of results of previous revegetation efforts, including:
(This should be done as applicable.)

1. Types (species) of seed that have germinated and are growing.

N/A

2. Types (species) of seed that are not growing successfully.

N/A

3. Areas experiencing problems with weeds and weed types.

None

4. Significant erosional problems.

None

5. Areas of unsuitable overburden on the surface as related to
revegetation failure.

N/A

6. Procedures used or proposed to correct these problems.

N/A

7. Acreage and dates of release (upon inspection by the State) of revegetated areas.

<u>Area</u>	<u>Date</u>	<u>Acreage</u>
None		

8. Results of soil analysis.

None

(e) Summarization of the reclamation costs incurred during the report period, including itemized costs for each operation (i.e., grading, topsoil replacement, seeding, etc.) and for each type of disturbance (i.e., spoil, haul roads, facilities removal, etc.) on a per acre basis.

	<u>Acres</u>	<u>Cost/Acre</u>
1. Grading	No reclamation work was done	
2. Backfilling	1984.	
3. Contouring		
4. Topsoil Replacement		
5. Seeding		
A. Seedbed Preparation		
B. Mulch		
C. Fertilizer		
D. Seed		
6. Other		

BOND INFORMATION:

- A. An updated bond estimate should be included, if required in the Division's approval of the Mining and Reclamation Plan (MRP) or if changes to the MRP have occurred, including a detailed itemization of actual/estimated reclamation costs as outlined in the RECLAMATION section above. The date of the release of revegetated areas from further responsibility for a partial bond release, if applicable, should also be included.

	<u>Amount</u>	<u>Type</u>	<u>Date Posted</u>
Present Bond	<u>8,811</u>	<u>Surety</u>	<u>February 15, 1983</u>

Increased disturbance, if any:

None

Increased Bond Amount (attached reclamation estimate). None

B. Bond release.

<u>Acres</u>	<u>Bond Amount Released</u>	<u>Date</u>
	<u>None</u>	

ADDITIONAL INFORMATION:

Supply any additional information as requested by the Division related to:

- (a) Permit stipulations (status).
- (b) Other special conditions (status).

Permit Status:

Permitting process was begun in previous years but never finalized. No annual reports have ever been prepared for this property before this 1984 report. A new MR Form 1 will be prepared on this property during 1985.